

## Obsolete Part Numbers for Compressor Valve Assemblies

As mentioned before in sales bulletin 265B dated August 2017, all stainless steel valve plates used in vertical compressor models 591, 691, 791, and 891 and all horizontal compressors with 5" and 6" cylinder sizes have been replaced with PEEK valve plates. Stainless steel valve plates are no longer available for the models mentioned above.

Effective immediately the following part numbers for valve assemblies with stainless steel valve plates are obsolete. Please make sure all future purchase orders reflect the new part numbers for PEEK valve plates shown below:

Obsolete Part Numbers (Stainless Steel)	Description	New Part Numbers (PEEK)
3856-X	Suction valve assembly, aluminum	3856-2X
3856-X1	Suction valve assembly, copper	3856-2X1
3856-X2	Suction valve assembly, iron-lead	3856-2X2
3856-1X	Suction valve assembly-light, aluminum	3856-3X
3856-1X1	Suction valve assembly-light, copper	3856-3X1
3856-1X2	Suction valve assembly-light, iron	3856-3X2
3857-X	Discharge valve assembly, aluminum	3857-2X
3857-X1	Discharge valve assembly, copper	3857-2X1
3857-X2	Discharge valve assembly, iron-lead	3857-2X2
3948-X	Suction valve assembly, spec 3, aluminum	3948-2X
3948-X1	Suction valve assembly, spec 3, copper	3948-2X1
3948-X2	Suction valve assembly, spec 3, iron	3948-2X2
3732-X	Suction valve assembly, aluminum	3856-2X
3732-X1	Suction valve assembly, copper	3856-2X1
3732-X2	Suction valve assembly, iron-lead	3856-2X2
3733-X	Discharge valve assembly, aluminum	3857-2X
3733-X1	Discharge valve assembly, copper	3857-2X1
3733-X2	Discharge valve assembly, iron-lead	3857-2X2

*Solutions beyond products...*

**CORKEN**<sup>®</sup>

CORKEN, INC. • A Unit of IDEX Corporation  
9201 North I-35 Service Road, Oklahoma City, OK. 73131 U.S.A.  
Phone (405) 946-5576 • FAX (405) 948-7343  
Visit our website at [www.corken.com](http://www.corken.com)  
E-mail us at [cocsalesdept@idexcorp.com](mailto:cocsalesdept@idexcorp.com)



@CorkenInc

