

New Full Rebuild Kit for All Z-Series Pumps

Rotor-Shaft Assemblies Included






When it comes to performing routine maintenance on a sliding vane pump, sometimes customers need a rotor-shaft assembly and sometimes they don't. In the past Corken has always offered the rotor-shaft assembly as separate item from the rebuild kit. To better accommodate all maintenance conditions, Corken now offers one repair kit and two types of rebuild kits. Rebuild kits are now available as a partial or full rebuild kit. The

only difference between the two is a full rebuild kit includes the rotor-shaft assembly and a partial does not. This addition to the Z-Series maintenance kit selections gives the customer more flexibility when servicing the pump. Additionally, the rotor-shaft assembly is less expensive when purchased through a rebuild kit.

The new full rebuild kit applies to all models Z2000, Z3200, Z3500, Z4200, and Z4500.



New Full Rebuild Kits for Z-Series Pumps

Models Numbers					
Part Numbers	3194-X3	3196-X3	3196-X4	3198-X3	
Contents	Each rebuild kit includes a rotor shaft assembly, two mechanical seals, three blade drivers, six blades, two sideplates, cam, cam key, shims, O-rings, two grease seals, two roller bearings, two thrust bearings, and two thrust bearing mounting rings.				